



Administrative Record for the US Department of Energy Rocky Flats Index

B705 - Building Cluster B705

Last updated: 9/26/2011

numerical index

B705-A-000001	8/14/2001
Documents discussions during tour of Building 705	
Purpose of Contact: Discusses the tour of Building 705 and the clean out preparation for characterization and closing the facility.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000001.PDF	64 KB

B705-A-000002	5/1/2003
Forwards RLCR for Building 705 for concurrence	
Forwards the attached [000003] Reconnaissance Level Characterization Report (RLCR) for Building 705, Revision 0 dated April 23, 2003 Type 2 facility for concurrence.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000002.PDF	77 KB

B705-A-000003	4/23/2003
RLCR for Building 705	
Reconnaissance Level Characterization Report (RLCR) Building 705, Revision 0 April 23, 2003. [Type 2]	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/Revised B705-A-000003.pdf	2 MB

B705-A-000004	4/24/2003
Submits the RLCR for Building 705	
Submits the attached [000003] Reconnaissance Level Characterization Report (RLCR) for Building 705, Revision 0 dated April 23, 2003 for approval.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000004.PDF	105 KB

B705-A-000005	7/17/2003
RLCR for Building 705 Type 2 Facility - Concurrence	
The Colorado Department of Public Health and Environment (CDPHE) concurs with the Reconnaissance Level Characterization Report (RLCR) Type 2 designation for Building 705, Revision 0 dated April 23, 2003.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000005.PDF	108 KB

B705-A-000006	12/9/2003
RSOP Notification for Building 705	

In accordance with the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Component Removal, Size Reduction (SR) and Decontamination Activities, this letter and its enclosure are notification for RSOP implementation. This notification is for component removal in Building 705. The work that will be undertaken under this notification is disconnection, packaging, and decontamination of equipment within building 705.

http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000006.PDF 495 KB

B705-A-000007

12/17/2003

Building 705 Notification of Component RSOP concurrence

The Colorado Department of Public Health and Environment (CDPHE), Hazardous Material and Waste Management Division has received December 9, 2003 letter notifying of the intent to utilize the Component Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for disconnection, packaging, removal, and decontamination of equipment and building surface within B705. CDPHE is hereby concurring that this activity may proceed utilizing the Component RSOP.

http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000007.PDF 120 KB

B705-A-000008

8/18/2004

Submits the enclosed RSOP for Facility Disposition Notification B705

Submits the enclosed RSOP for Facility Disposition Notification Letter for Building 705.

http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000008.pdf 403 KB

B705-A-000009

8/23/2004

Forwards the enclosed Facility Disposition RSOP Notification, B705

Forwards the enclosed Facility Disposition RSOP Notification Letter for Building 705, identified as a Type 2 facility based upon radiological contamination. This notification invokes the RSOP for demolition of the facility. In addition, the Pre-Demolition Survey Report (PDSR) is also enclosed for review and concurrence. All surfaces meet the PSDP unrestricted release criteria.

http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000009.pdf 2 MB

B705-A-000010

7/29/2004

Dirty Demolition of Building 705

Purpose of Contact: Dirty Demolition of Building 705. Prior to the beryllium abatement process in Building 705, beryllium concentration was as high as 779.0 ug/100cm² with a number of samples showing concentrations in the range of 8.5 to 145.0 ug/100cm². The beryllium cleaning process in Building 705 included vacuuming, then an application of CC Wet, followed by wiping with clean dry towels in areas not exceeding 6 to 8 square feet at a time.

http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000010.pdf 71 KB

B705-A-000011

8/30/2004

RE: PDSR for Building 705

The Colorado Department of Public Health and Environment (CDPHE), Hazardous Material and Waste Management Division has reviewed the Pre-Demolition Survey Report (PDSR) for Building 705, Revision dated August 17, 2004. This PDSR was received on August 27, 2004. Based on the information contained in this PDSR, CDPHE is hereby approving the PDSR for Building 705.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000011.pdf	91 KB
B705-A-000012	8/30/2004
RE: B705 Facility Disposition RSOP Notification	
The Colorado Department of Public Health and Environment (CDPHE), Hazardous Material and Waste Management Division has reviewed US Department of Energy (DOE), August 23, 2004 letter (received on August 27, 2004) notifying CDPHE that the Facility Disposition Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) Notification will be utilized during the demolition of Building 705. We hereby agree that may be demolished utilizing the Facility Disposition RSOP and as described.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000012.pdf	83 KB
B705-A-000013	2/21/2005
Transmittal of the Final Closeout Report for Building 705	
The attached [000014] copies of the Final Closeout Report for the Type 2 Building 705. The report is submitted to document completion of Deactivation and Decommissioning (D&D) activities for Building 705. Transmittal to the Colorado Department of Public Health and Environment (CDPHE) and the US Environmental Protection Agency (EPA), in accordance with the Rocky Flats Cleanup Agreement (RFCA) is requested.	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000013.pdf	73 KB
B705-A-000014	2/21/2005
Final Project Closeout Report for Building 705 Revision 0, February 2005	
Final Project Closeout Report for Building 705 Revision 0 February 2005. Closure of the facility was completed in accordance with the Rocky Flats Cleanup Agreement Standard Operating Protocol (RFCA RSOP).	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000014.pdf	1 MB
B705-A-000015	4/19/2005
Re: D&D Closeout Report for Building 705 Approval	
The Decontamination and Decommissioning (D&D), Closeout Report for Building 705. The Colorado Department of Public Health and Environment (CDPHE), Hazardous Materials Code (HM) and Waste Management (WM) Division has reviewed, US Department of Energy (DOE) letter and the Closeout Report for Building 705, dated March 17, 2005. Building 705 was previously determined to be a Type 2 Facility. As such and base on the information provided (and discussion with Kaiser-Hill Company, L.L.C. (K-H), CDPHE are here by approving this D&D Closeout Report for Building 705	
http://www.lm.doe.gov/cercla/documents/rockyflats_docs/B705/B705-A-000015.pdf	63 KB